



Head  
Protection



Respiratory  
Protection



Fire and Rescue  
Safety



Thermal  
Imaging


**Bullard Type I hard hats and caps have been tested and found to be compliant to the requirements of the ANSI Z89.1-2003 standard when worn with the shell turned backward.**

To perform properly in this manner, the suspension must be reversed in the helmet, so that the headband is oriented normally to the wearer's head (i.e., with the brow pad against the forehead and the extended nape strap at the base of the skull). In this manner, only the shell of the helmet is backwards on the head.

This applies to Z89.1-2003 Type I hats and caps only (Bullard models 3000, 302RT, 303, 5100, 4100, 502, 911C, 911H, and 5100P).

**Type II helmets (Advent and Vector) should not be worn backward** because of the lower rear edge of the shell and the asymmetrical pattern of protection offered by their more complex design.

If any of this is unclear, or if you have further questions, please feel free to call Bullard Customer Service at 877-BULLARD (285-5273).



**Bullard**  
1898 Safety Way  
Cynthiana, KY 41031-9303  
Toll free: +877-BULLARD (285-5273)  
Tel: +859-234-6616  
Fax: +859-234-8987  
[www.bullard.com](http://www.bullard.com)

**Bullard GmbH**  
Hochkreuzallee 36  
53175 Bonn-Bad Godesberg  
Germany  
Tel: +49 228 931933 0  
Fax: +49 228 931933 50



ISO 9001  
certified